Professional RV Care #4

110 S. Cherokee Lane, Suite B, Lodi, CA 95240
Contact: Dustin **Phone:** 209-263-7040
E-mail: calrv@att.net
Website: www.calrvspecialists.com

Exterior Detail Services

WASH EXTERIOR .....

15'- 25'	**$175.00**
26'- 30'	**$200.00**
31'- 35'	**$225.00**
36'- 40'	**$250.00**

- Pressure wash roof surface
- Scrub and hand wash body
- Squeegee and wipe down windows
- Scrub, clean and apply tire dressing

WASH & WAX .....

15'- 25'	**$800.00**
26'- 30'	**$1,000.00**
31'- 35'	**$1,200.00**
36'- 40'	**$1,400.00**

- Pressure wash roof surface
- Scrub and hand wash body
- Apply wax to exterior body
- Squeegee and wipe down windows
- Scrub, clean and apply tire dressing

PRICE VARIES SUBJECT TO INSPECTION

CLEAN UP & INSPECTION .....

15'- 25'	**$1,750.00**
26'- 30'	**$2,000.00**
31'- 35'	**$2,250.00**
36'- 40'	**$2,500.00**

- 45 point inspection
- Pressure wash roof and exterior body
- Spot seal exterior roof, window and moldings
- Remove/Replace insert molding/screw covers as needed
- Remove/Replace drain gutter drip caps
- Remove/Replace entry door window trim rings, hold backs and bumpers
- Paint all plastic discolored doors and covers (white)
- Remove/Replace all discolored clearance and entry door light lenses
- Remove/replace compartment door hold backs/latches
- Paint rear bumper, trailer A-frame, or 5th wheel pin box and entry door steps
- Lube slide out rails and seals **(if equipped)**

PRICE SUBJECT TO INSPECTION

Interior Detailing

WE OFFER THE FOLLOWING SERVICES AT $110.00 per HOUR:

- Vacuum carpeting
- Shampoo carpeting
- Mop and scrub flooring
- Clean and condition leather seating
- Clean and protect fabric seating
- Clean appliances, refrigerator, stove/oven
- Clean interior windows
- Clean wall surfaces
- Clean lighting fixtures and ceiling fans
- Clean full bathroom
- Clean full kitchen
- Clean sleeping areas
- Clean countertops
- Clean cabinet surface and finishes

Oxidation Removal

WE OFFER THE FOLLOWING SERVICE AT $110.00 PER HOUR:
***ALL MATERIALS CHARGES SEPARATELY**
(including wool/foam pads and rags)

This service is required for RVs with gel coat or fiberglass finishes with light to severe oxidation or rading.

We will attempt to remove all oxidation as possible.
In most cases this is a four step process to completely restore your RV finish:

1. Proprietary process to eliminate all build-up and residue on gel coat / fiberglass.
2. High speed polish with rubbing compound [wool pads required].
3. Low speed polish to remove swirls. [foam pads required].
4. Finish with an application of carnauba wax or gel coat sealer.

*This service includes an exterior wash.

Average cost range is $1,500.00 - $3,000.00 depending on unit size and condition.